٦Ì,

Amendments to the Specification

Please amend the paragraph bridging pages 20 and 21 in the following manner:

If the call operation for the available specific service is not properly completed and the check result of Step S108 is NO, the process proceeds to Step S109 in which the system controller 2 further checks if the cause of the improperly-completed call operation is incorrectness of the corresponding pertinent information. If the cause of the improperly-completed call operation is incorrectness of the pertinent information and the check result of Step S109 is YES, the process proceeds to Step S111 in which the system controller 2 reads and stores the corresponding dummy code of the self-notification call-disconnection-cause registered in the specific service registration table 7a. Then, the process proceeds to the call-disconnection process in Step S201 (Fig. 7B).

Please amend the paragraph at page 26, lines 3-9 in the following manner:

Fig. 17 shows another exemplary procedure of the notification of the contents and the guidance performed in Step S507. In Step S701 of Fig. 17, the system controller 2 extends in the image memory 8 the image data of the error report containing the information of the contents and the guidance specified in Step S506 of Fig. 14, using the font table 3a, so as to generate a bit-mapped image of the error report. Then, the system controller 2 instructs the printer 6 to print the error report, in Step S702. The process then end ends.